Incident Summary #II-1648621-2023 (#42362) (FINAL)

inc	Incident Summary #II-1648621-2023 (#42362) (FINAL)					
SUPPORTING INFORMATION	Incident Date		December 8, 2023			
	Location		Ladysmith			
	Regulated industry sector		Electrical - Low voltage electrical system (30V to 750V)			
		Qty injuries	0			
	t Injury	Injury description	Canine – deceased.			
	Impact	Injury rating	None			
	Im	Damage description	Melted heater, fire damage to walls and floor in room of origin. Fire spread to walls and basement damaging structural components.			
		Damage rating	Moderate			
	Incident rating		Moderate			
	Incident overview		A fire started in the vicinity of a baseboard heater. The fire damaged the floor and walls in the room of origin and spread through a vent in the floor to the basement. A 10-month-old Canine in the room perished.			
	Site, system and components		A baseboard heater (BB heater) is an electric heater that uses a resistor/element and convection to heat a room.			
			The heaters are usually mounted under windows as this aids in the natural convection process.			
INVESTIGATION CONCLUSIONS			Manufacturer's instructions specifically state that users are to keep flammable materials away from the heaters and have specific clearances that are to be maintained for items like drapes or furniture. Manufacturer's instructions will also have restrictions on the type of material that the heaters can be mounted to. This brand of heater was restricted from being mounted to Low Density Fiberboard (LDF).			
			The bedroom where the fire started had a 1000-watt BB heater mounted to a fir baseboard. Positioned directly in front of the heater was a floor vent that opened directly to the basement. Underneath the vent in the basement were shelves full of empty plastic bottles. The floor vent was not connected to furnace ducting.			
	Failure scenario(s)		The room where the fire started was being used to house a 10 month of canine. The canine succumbed to smoke inhalation. There were several dog toys in the vicinity of the heater, one was half burnt on the floor and several that were positioned on the windowsill above the heater were melted.			
			It is thought by investigators, that flammable material contacted the heater which ignited and was able to spread to the plastic bottles stored on the shelves underneath the heater through the floor vent, as the furnace duct was disconnected from the vent.			
			No other electrical sources were found in the vicinity of the fire origin, in the bedroom nor in the basement under the bedroom.			

Incident Summary #II-1648621-2023 (#42362) (FINAL)

Facts and evidence	Independent fire investigators examined the scene and noted that based on the smoke pattern on the wall, that the curtains were open when the fire started. The heater was mounted directly to a fir baseboard which complied with the manufacturer's instructions. Investigators stated that the fire originated at the heater and likely had flammable material up against it.
Causes and contributing factors	It is plausible that flammable material contacted the heater, which ignited and spread to the basement through the vent in the floor.



Image 1 - Front of house, fire started in the bedroom to the left of the main entrance.





Image 2 - Origin of the fire.

Technical Safety BC www.technicalsafetybc.ca





Image 3 - Shelving in the basement under the bedroom, the shelving contained plastic bottles.

Technical Safety BC www.technicalsafetybc.ca






Image 4 - Looking from bedroom through hole in floor to the basement.