

Incident Summary (Reference #5583910) (Final)

SUPPORTING INFORMATION	Incident Date		March 17, 2016	
	Location		Kelowna	
	Regulated industry sector		Passenger Ropeways - Above Surface	
	Impact	Injury	Qty Injuries	0
			Injury description	N/A
			Injury rating	N/A
	Damage		Damage description	33 mm long crack in tower cross arm, that was repaired using the manufacturers repair procedure.
			Damage rating	Minor
	Incident rating		Minor	
Incident overview		While conducting a visual inspection of tower one a 33 mm long crack was found in the tower cross arm. This inspection was being conducted as a follow up to a manufacturers safety bulletin.		
INVESTIGATION CONCLUSIONS	Site, system and components		4 person detachable high speed chairlift. Steel cross arm of a tubular steel tower used to support chairlift components.	
	Failure scenario(s)			
	Facts and Evidence			
	Causes and Contributing Factors			



Tower 1 uphill side.