



Multimeter test pen (black + red)

2



BNC to 4mm Test Leads

3



Type A to Type B USB Cable

4



Power adapter

5




Max4scope

1




6

Multimeter probes (red)




7

Multimeter probes (black)




8

Back Probe Pins Suite



9

Crocodile clips (black)



10

Crocodile clips (red)

