

# Industrial-Strength Cleaner & Resin Remover

---

(56Z43.01)

Removes burnt-on resin from saw blades.

General cleaner for caked-on grease and grime.

## **Instructions:** Dilution Ratios

Undiluted, it should not be used on painted surfaces or on aluminum. To remove burnt-on resin, or caked-on grease and dirt, apply full strength, let sit a minute or two and wipe off. Rinse with water.

For heavy, loose build-up dirt, grease and grime, use 10 parts water to 1 part cleaner.

For general cleaning on finished surfaces, use 100 parts water to 1 part cleaner.

**Protection:** Wear neoprene gloves, plastic apron and splash-proof goggles or full face shield.