



**PRODUCT RECALL: Element II, 12-Gauge Shotguns**

Dear Consumer,

Weatherby Inc. is announcing a voluntary recall of certain Element 2, 12 Gauge Shotguns, which fall between the following Serial Number ranges:

TR7825-RL000001 – TR7825-RL001260	TR7825-RL012571 – TR7825-RL012870
TR7825-RL002762 – TR7825-RL004926	TR7825-RL013171 – TR7825-RL013770
TR7825-RL007849 – TR7825-RL007850	TR7825-RL015522 – TR7825-RL016120
TR7825-RL007854	TR7825-RL016521
TR7825-RL008455 – TR7825-RL008954	TR7825-RL016523
TR7825-RL009055 – TR7825-RL009103	TR7825-RL017024 – TR7825-RL017223
TR7825-RL010005 – TR7825-RL010104	TR7825-RL017225 – TR7825-RL017273
TR7825-RL012271 – TR7825-RL012521	TR7825-RL019401 – TR7825-RL019500

Weatherby was notified by one of its suppliers that the **Bolt Head** may have been improperly heat treated and, therefore, does not conform to Weatherby’s specifications. Improper heat treatment could result in the Bolt Head fracturing after firing.

Weatherby is offering, at no cost to the customer, to (a) send a replacement Bolt Head for your installation or (b) replacement of the Bolt Head of the returned Bolt Assembly should you choose to have Weatherby perform the replacement. ***Until the Bolt Head is replaced, use of the shotgun should immediately stop as continued use may result in damage to the shotgun, bodily injury, or injury to others.***

**Consumer Contact**

To contact Weatherby regarding replacing the BOLT HEAD of your Element II shotgun, please either

- (a) call us at 307-675-7840
- (b) email us at [consumerservices@weatherby.com](mailto:consumerservices@weatherby.com)
- (c) fill out the Remedy Request form on our website <https://weatherby.com/element-2-safety-recall/> or scan the QR

Respectfully,

Weatherby Team

