

VOLUNTARY SAFETY RECALL

Breville Fast Slow Cooker (BPR600XL) Lid Gasket

Domestic programmable stainless steel electric pressure cooker



Identification

- Units sold between October 2012 and October 2015 through retailers and department stores nationally.
- Production date code (PDC) 1238, 1311, 1316, 1333, 1346, 1328, 1352, 1412, 1426, 1427, 1437, 1451, 1505, 1527.
- Only BPR600XL units with a white silicone lid gasket are affected.

Hazard: Scalding - incorrect fitting of the supplied white lid gasket may result in release of hot liquids.

Defect: A potential risk has been identified if the lid gasket is not installed properly.

If you would like to order your free new lid gasket, please click on the link below:

<http://www.breville.ca/lidrecall>

You may also email us at productsafety@breville.ca to request your free new lid gasket for model BPR600XL or contact us at 1-855-683-3535 (8:30am-5:00pm Eastern Time, Monday-Friday).