

## Incident Summary (5578842) (Final)

SUPPORTING INFORMATION	Incident Date		February 24, 2016	
	Location		Invermere	
	Regulated industry sector		Above-surface passenger ropeways	
	Impact	Injury	Qty Injuries	0
			Injury description	N/A
			Injury rating	None
	Damage		Damage description	N/A
			Damage rating	None
	Incident rating		Insignificant	
Incident overview		Passenger unloading from a chairlift swung the carrier excessively this caused the carrier to swing in and impact with the guide sheave assembly. This impact caused the haul rope to derope and be retained by the haul rope deropement catcher.		
INVESTIGATION CONCLUSIONS	Site, system and components		N/A	
	Failure scenario(s)		N/A	
	Facts and Evidence		N/A	
	Causes and Contributing Factors		N/A	