

## Incident Summary (Reference #5580764) (Final)

SUPPORTING INFORMATION	Incident Date		March 5, 2016	
	Location		Whistler	
	Regulated industry sector		Passenger Ropeways – Above Surface	
	Impact	Injury	Qty Injuries	0
			Injury description	N/A
			Injury rating	None
	Damage		Damage description	None
			Damage rating	None
Incident rating		Insignificant		
DESCRIPTION	Incident overview		4 passengers were attempting to load onto a carrier, the passenger on the far left side was struggling and interfered with the passenger to their right. This prevented that passenger from sitting on the carrier correctly. The lift operator recognized the situation and stopped the ropeway. The passenger ended up hanging from the carrier just outside the station, the lift operator deployed the fireman's net and the passenger dropped approximately 2.5 meters to the net.	
	Site, system and components		Recreational Ski Area Bottom station load ramp of a 4 passenger high speed detachable grip chairlift	
CONCLUSIONS	Failure scenario(s)		NA	
	Facts and Evidence		NA	
	Causes and Contributing Factors		NA	