

Incident Summary (5581004)

SUPPORTING INFORMATION	Incident Date		February 17, 2016	
	Location		Invermere	
	Regulated industry sector		Passenger Ropeways – Above Surface	
	Impact	Injury	Qty Injuries	0
			Injury description	N/A
			Injury rating	None
	Damage		Damage description	N/A
			Damage rating	None
	Incident rating		Insignificant	
	Incident overview		Passenger did not unload correctly from the chairlifts carrier, this caused the carrier to swing excessively. The swinging caused the carrier hanger arm to impact with the guide sheave assembly. This resulted in the haul rope deroping from the sheaves and landing in the haul rope deropement catcher.	
INVESTIGATION CONCLUSIONS	Site, system and components		N/A	
	Failure scenario(s)		N/A	
	Facts and Evidence		N/A	
	Causes and Contributing Factors		N/A	