

SAFETY RECALL

GLW Battery Packs Installed in Razor Hovertrax 2.0 Hoverboards



Hazard: The recalled lithium-ion GLW battery packs can overheat, posing a risk of smoking, catching fire and/or exploding.

Description: This voluntary recall involves GLW battery packs installed in Hovertrax 2.0 hoverboards built between September 2016 and August 2017. The name GLW is on the battery pack. The recalled battery packs have serial numbers beginning with GLW. The serial number is located on a white sticker on the top of the battery pack below the bar code.

What to do: Stop using the Razor Hovertrax 2.0 immediately and contact Razor to arrange to return your GLW battery pack to Razor and to receive a free replacement battery pack by calling

866-467-2967

between 8:00 am and 5:00 pm Pacific Time, Monday through Friday or visit www.razor.com and click on CPSC Safety Recalls for more information.