



Dear Valued Evenflo Retailer:

Please be advised that Evenflo Company, Inc. ("Evenflo") has decided, as of April 30, 2014, to recall select 2011-2014 convertible and harnessed booster seats, identified below by name and date of manufacture. In many instances, these products have already been sold through your inventory. All products currently being shipped or manufactured for you are unaffected by this recall.

***PLEASE CONSULT THE ATTACHED EXHIBIT A FOR THE IMPACTED SKU LIST.**

Model Names*	Affected Dates of Manufacture*
Momentum 65 DLX	5/1/2013-5/31/2013
Chase LX and DLX	10/28/2011- 10/3/2013
Maestro	10/3/2011 - 10/17/2013
Symphony 65, LX, DLX and Snugli All-in-One	11/30/2012 - 8/26/2013
SureRide DLX	6/1/2013 - 6/24/2013
Secure Kid LX, 400 and Snugli Booster	1/1/2012- 2/6/2014

The date of manufacture is located on the white 4x3 bar code shipping label on the seat carton. The date is in year/month/day format. On the Symphony car seat label below, 2014/02/24 is a manufacturing date of February 24, 2014; therefore, this seat would not be subject to recall.



These select models use a harness crotch buckle which may become resistant to unlatching over time, due to exposure to various contaminants, like food and drinks. This condition may make it difficult to remove a child from the vehicle. There is no such risk if the buckle is functioning normally. These seats meet all requirements for crashworthiness under CMVSS 213.

Evenflo is providing at no charge to the consumers who have own affected seats a remedy kit that includes a replacement buckle and instructions for installation. The remedy kit is available by contacting Evenflo at www.buckle.evenflo.com or 1-800-490-7591. We have asked consumers not to return these seats to retailers.

Please note that it is a violation of law for a retailer to sell or deliver any affected product covered by this recall unless the product is remedied. Please contact your Evenflo sales representative with questions about this recall. In addition, we are enclosing a recall poster that you may post in a prominent location.

We anticipate that with our support efforts we can minimize the disruption this recall may cause and move forward with our growing partnership.

EXHIBIT A (L'ANNEXE A)

MODEL NAME/NUMBER NOM DE MODÈLE/NUMÉRO	IMPACTED DATES OF MANUFACTURE / DATES DE FABRICATION CONCERNÉES
Momentum 65 DLX	
3853998C	5/1/2013-5/31/2013
Chase LX, DLX	
30611117C	7/1/2012-10/3/2013
30611377C	7/1/2012-10/3/2013
32911122C	10/28/2011-4/30/2012
32921139C	11/4/2011-1/31/2012
32921144C	11/4/2011-11/30/2011
Maestro	
31011196C	10/3/2011-10/17/2013
31011270C	4/1/2012-10/17/2013
31011277C	11/1/2011-1/1/2013
31011277CD	12/1/2011-12/31/2012
31011433C	12/1/2012-10/17/2013
31011433CD	12/1/2012-12/31/2013
3101964C	12/1/2012-10/17/2013
3101964CD	12/1/2012-4/30/2013
3102979C	10/3/2011-5/31/2012
Symphony DLX, 65, LX /Snugli All in One	
34511125C	11/30/2012-1/17/2013
34511264C	11/30/2012-8/26/2013
34511266C	11/30/2012-8/26/2013
34611038C	11/30/2012-3/5/2013
34611341C	1/31/2013-8/26/2013
34611358C	11/30/2012-3/5/2013
34611364C	1/31/2013-8/26/2013
34611376C	11/30/2012-3/5/2013
34621038C	1/25/2013-8/26/2013
34621358C	1/30/2013-8/26/2013
34621376C	1/30/2013-8/26/2013
SureRide DLX	
37111324C	6/1/2013-6/24/2013
Secure Kid LX, 400/Snugli Booster	
30811162C	5/1/2013-11/15/2013
30811229C	12/1/2013-2/6/2014
30811229CD	1/1/2014-1/16/2014
30811269C	1/1/2012-1/31/2013
30811342C	6/1/2013-11/14/2013
30821269C	2/1/2013-6/25/2013