

## IMPORTANT SAFETY NOTICE

According to our records, you may have purchased a Bionaire oil filled heater Model BOF2001-CN or a Sunbeam oil filled heater Model SOF1000-CN in 2014 that may be affected by a recall initiated by Sunbeam. This recall is being conducted in cooperation with Health Canada. It has been determined that the products pose a scald hazard. **Please stop using these products immediately.**

Please carefully review the instructions being provided on how to determine if your heater is subject to the recall and how to participate in the recall program. The only products affected have a date code on the heater plug prong of G170, G179 or G229. No other date codes are affected.

**If your heater is subject to the recall, please stop using it immediately and do not use it again. If you have any questions or concerns, please contact Sunbeam at (800) 515-4715 anytime or visit [www.bionaireB2001recall.ca](http://www.bionaireB2001recall.ca) or the brand website [www.bionairecanada.com](http://www.bionairecanada.com) or <http://www.sunbeam.ca/> for more information.**



Sunbeam very much regrets any inconvenience this may cause you. We are taking this action to be absolutely certain you have the safest, most reliable product available. We thank you for your patience and extend our sincere appreciation for taking your time to participate in this recall program.

Very truly yours,  
Sunbeam Corporation (Canada) Ltd.