

Safety Recall Notice

Vitamix Ascent[®] and Venturist[™] Series 8-ounce and 20-ounce blending containers

The container may separate from the blade base, exposing the blades to consumers and creating a laceration hazard.

Containers with blade manufacture dates 03-18 (March 2018) or prior are affected. If the blade base is marked on the bottom with a green or orange dot, the container has already been repaired.



If your product is included, **STOP USING IT IMMEDIATELY** and call Vitamix toll-free

888-847-8842

between 7:00 a.m. and 6:00 p.m., Central Time, Monday through Friday or visit www.recallrtr.com/blender for information on a free repair kit.