

Appendix B

Evidence Reviewed

The following relevant evidence was gathered and reviewed as part of this investigation:

- Bridal Falls Waterpark General Operating Guidelines 2024.
- Bridal Falls New and Young Worker Orientation 2024.
- Bridal Falls Waterpark Opening & Closing Procedures and Operations Position Descriptions 2024.
- Bridal Falls Waterpark Slide Operations Manual.
- Bridal Falls Waterpark Pool Safety Plan 2024.
- Waterpark staff sign in/sign out sheet for July 14, 2024.
- Bridal Falls Waterpark Staff Orientation sign off sheets for 2024.
- Bridal Falls Waterpark Lead orientation manual, undated.
- Bridal Falls Waterpark Orientation and Training Manual, undated.
- Bridal Falls Waterpark Incident Reports from 2022 to 2024.
- Bridal Falls River Rapid Pre-Opening Checklist.
- Bridal Falls Daily Inspection form for all waterslides at the Waterpark from June 1 to July 14, 2024.
- Bridal Falls Incident Report from slide attendant [REDACTED] for the leg injury incident dated July 14, 2024.
- Bridal Falls Incident Report from office worker [REDACTED] for the leg injury incident dated July 14, 2024.
- Bridal Falls Incident Report from Lead [REDACTED] for the leg injury incident dated July 14, 2024.
- Additional Bridal Falls Incident from Lead [REDACTED] and Office Manager [REDACTED] for the foot injury incident, dated July 14, 2024.
- Bridal Falls Incident report from Lead-in-training [REDACTED] for the ankle injury incident, dated July 14, 2024.
- First aid certificates for Bridal Falls workers with first aid training on site on July 14, 2024.
- Interview with [REDACTED], owner of Versatile Waterparks, and fiberglass contractor for the waterpark on July 25, 2024.
- Interview with [REDACTED], General Manager for the Waterpark on July 25, 2024 and again on September 9, 2024.
- Interview with [REDACTED], Slide Attendant at the Waterpark, July 25, 2024.
- Interview with [REDACTED], Lead at the Waterpark, on July 25, 2024.
- Interview with [REDACTED], VP Operations for Holiday Trails (owner of the Waterpark), on July 16, 2024 and July 31, 2024.
- Interview with [REDACTED], Partner/CEO of Waterfun Products, the original manufacturer of the Tube Slide on July 30, 2024.
- Interview with [REDACTED], Lead-In-Training at the Waterpark, on July 25, 2024 and again on September 4, 2024.
- Interview with [REDACTED], Lead at the Waterpark, on July 25, 2024.
- Interview with [REDACTED], Office Manager at the Waterpark, on August 8, 2024.
- Interview of [REDACTED], whose foot was injured on July 14, 2024, on August 2, 2024.

- Written responses to questions from the 11-year-old injured in the Incident, [REDACTED] on August 12, 2024.
- Interview of [REDACTED], who received an abrasion and bathing suit tear on the Tube Slide on July 14, 2024, on August 6, 2024.
- Interview of [REDACTED], whose child received an abrasion and torn bathing suit on July 14, 2024, on August 6, 2024.
- Facebook Social media posts from the Bridal Falls Facebook page regarding injuries sustained on July 14, 2024.
- Facebook Social Media posts from the group “Chilliwack moms group” regarding the tube ride.
- Google reviews posted after the incident regarding the Tube Slide.
- E-mail from VP of operations for Bridal Falls Waterpark regarding maintenance invoices for the Tube Slide, dated January 15, 2024.
- BC Recreational Pool Association Pool Operator Level 1 and II participant manuals.
- CSA Z-267 Safety Code for Amusement Rides, 1983 and 2000 editions.
- Onsite inspection of the Tube Slide by Technical Safety BC Safety officer on July 16, 2024.
- Onsite inspection and documentation of the Tube Slide by Technical Safety BC Senior Safety officer, and Leader of Incident Investigations on July 25, 2024.
- Onsite inspection and documentation of the Tube Slide by Technical Safety BC Leader, Incident Investigations on August 13, 2024
- Eight (8) Photographs submitted by [REDACTED], owner of versatile waterparks, from prior to, and during removal of the failed section of slide, from July 15, 2024.
- Four (4) Photographs submitted by [REDACTED], Lead at the Waterpark, of the failure, taken on July 14, 2024, immediately post-incident.
- Three (3) photographs submitted of abrasions received by [REDACTED] and her family from the Tube Slide on July 14, 202, submitted August 7, 2024.
- Two (2) photographs submitted to the Safety Officer of the failure on July 14, 2024 by a member of the public.
- YouTube videos of patrons progressing down the Tube Slide while it is in operation, reviewed July 24 and August 13, 2024.
- Materials Analysis Report Completed by Acuren Inc. following analysis of multiple sections of Fiberglass form the Tube Slide, including the failed area, dated October 11, 2024.
- Technical Safety BC Contractor License Approval for Trans Canada Waterslides (DBA Bridal Falls Waterpark) dated February 5, 2024.
- Technical Safety BC Certificates of Inspection, 2004 to 2024.
- Waterslide Operation and Maintenance Manual for a 2018 slide from a prominent waterslide manufacturer.